https://www.wago.com/207-4301





Your Benefits:

- Simple, quick and safe connection of up to 60 conductors
- A clearly structured arrangement that's secured on one level
- Highly visible labeling for each individual connection point

Physical data	
Width	225 mm / 8.858 inches
Depth	145 mm / 5.709 inches

Material data		
Note (material data)	Information on material specifications can be found here	
Color	white	
Cover color	white	
Insulation material	Polycarbonate (PC)	
Flammability class per UL94	V0	
Fire load	0 MJ	
Weight	422.7 g	
Environmental requirements		
Ambient temperature (operation)	-25 +85 °C	
Ambient temperature (storage)	-25 +85 °C	

Commercial data	
ETIM 8.0	EC001170
ETIM 7.0	EC001170
PU (SPU)	1 pcs
Country of origin	CN
GTIN	4055144019247
Customs tariff number	39269097900







Data Sheet | Item Number: 207-4301

https://www.wago.com/207-4301

Environmental Product Compliance

RoHS Compliance Status



Compliant,No Exemption

Approvals / Certificates

General approvals

KEUR		
Approval	Standard	Certificate Name
KEMA/KEUR DEKRA Certification B.V.	EN 60670	71-113202

Declarations of conformity and manufacturer's declarations

Approval	Standard	Certificate Name
EU-Declaration of Confor- mity WAGO GmbH & Co. KG	-	-
UK-Declaration of Confor- mity WAGO GmbH & Co. KG	-	-

Downloads
Environmental Product Compliance
Compliance Search
Environmental Product Compliance 207-4301

Documentation	
Bid Text	
ausschreiben.de 207-4301	\downarrow

CAD/CAE-Data

CAD data	
2D/3D Models 207-4301	$\underline{\checkmark}$

1 Compatible Products		
1.1 Optional Accessories		
1.1.1 Marking		
1.1.1.1 Marking strip		
Q.		

Item No.: 2009-110 Marking strips; for Smart Printer; on reel;

not stretchable; plain; snap-on type; white

Data Sheet | Item Number: 207-4301

https://www.wago.com/207-4301

1.1.2 Strain relief

1.1.2.1 Specific accessories



Item No.: 207-9301 Accessories set; Strain relief and marking; for junction box; Item 207-4301

Installation Notes

Installation



The junction box is designed for surface screw mounting on the wall/ceiling. The cover can be snapped on and off without screws. The connectors are easily mounted by snapping them in, and the marking strips are mounted by simply pushing them in.



Snap the connector into the holder.



Release the connector from the holder.

Conductor termination



Inserting a conductor

Marking



Snap the marking strips into the holder.

Installation



Insert the cable into the strain relief. The snap-in strain reliefs are designed for cable diameters from 4 mm to 11 mm.



Break the cable entry lid out of the cover.



Snap on the junction box cover.



Open the junction box cover.

Subject to changes. Please also observe the further product documentation!

Current addresses can be found at:: <u>www.wago.com</u>